

## **Safety Precautions**

## **PF32 Mounting Plate Installation Guide**



• This guide explains how to install the mounting plate using the screw fixing method. Structural adhesive fixing is another option, but this guide focuses solely on screw fixing.

• The mounting plate is pre-installed on the back of the screen at the factory. Users must prepare Accessory 3 independently.




- Refer to the provided installation diagram and included accessories.
- Follow the installation steps as a reference.
- Ensure all screws are securely tightened.
- Use the equipment within the specified size and weight limits for safety.
- Install on a flat wall.
- Important: For wooden walls, ensure the wall thickness is at least 3 cm and the load-bearing capacity is 100 kg.
- Suitable for 32" installations.


## **Installation Steps**




1 Secure the mounting plate to a solid, load-bearing wall using M4 screws  $\times$  6.

For vertical installation, the "UP" label on the short side of the mounting plate should face upwards. For horizontal installation, the "UP" label on the long side of the mounting plate should face upwards. After installation, the mounting plate will be geometrically symmetrical relative to the machine, with the center of the cross-dashed line marking the center of both the plate and the machine. This alignment ensures consistency and allows customers to create custom fixtures for future installations.









Whilst supporting the screen with your hands, let it slide downwards to the turning point of the mounting plate, as shown in the installation diagram and push the screen toward the right until it locks into place.

(Note: The diagram shows the front view of the machine. The mounting plate and its L-shaped holes are fixed to the wall. Only the machine, with its hanging nails, moves during this step.)

